Appl. No. 10/624,829

Amdt. dated February 3, 2006

Reply to Office Action of October 5, 2005

Amendments to the Specification:

Please replace the paragraph [0004] with the following rewritten paragraph [0004]:

[0004] ECC's may detect single- and multi-bit errors in a data stream. Single-bit errors are most often caused by a random transient event. ECC's also have the ability to correct most single-bit errors, allowing the system to operate without downtime attributable to correctable single-bit errors.

However, there are certain types of single-bit errors that are uncorrectable. These uncorrectable single-bit errors are sometimes referred to as "sticky bits." A "sticky bit" usually is the result of a physical problem in the memory device. A "sticky bit" does not always changes state when requested. In addition, there are multi-bit errors that are typically uncorrectable. The multi-bit errors may be the result of a physical problem in the memory device, like a "sticky bit," or they may be the result of some other random transient event.

Please replace the paragraph [0006] with the following rewritten paragraph [0006]:

[0006] In order to To improve the reliability and availability of a such a system, what is needed is a solution that may, upon identification of an uncorrectable error, switch to a redundant backup memory system so that the system may continue operating without downtime. In addition, what is needed is a solution that is able to test the memory device to determine if the uncorrectable error is due to a physical problem with the memory device, or due to a random transient event.

GUNNISON, McKAY & HODGSON, L.L.P. Garden West Office Plaza 1900 Garden Road, Suite 220 Monterey. CA 93940 (831) 655-0880 Fax (831) 655-0888